

# PROPRESSG



## BRONZE ADAPTER C x M NPT

Use male adapters to transition between copper and female NPT connections. All fittings come with the Smart Connect Feature.

Stock Code	Part Description	Bag Quantity	Box Quantity	Approx. wt./lb. Each
16043	1/2" C x 3/8" M NPT	10	300	0.10
16048	1/2" C x 1/2" M NPT	10	200	0.15
16053	3/4" C x 3/4" M NPT	10	150	0.20
16058	1" C x 1" M NPT	10	110	0.35
16063	1-1/4" C x 1-1/4" M NPT	1	60	0.55
16068	1-1/2" C x 1-1/2" M NPT	1	35	0.75
16073	2" C x 2" M NPT	1	25	1.15



## BRONZE ADAPTER C x F NPT

Use female adapters to transition between copper and male NPT connections. All fittings come with the Smart Connect Feature.

Stock Code	Part Description	Bag Quantity	Box Quantity	Approx. wt./lb. Each
16078	1/2" C x 1/2" F NPT	10	170	0.15
16083	3/4" C x 1/2" F NPT	10	180	0.15
16088	3/4" C x 3/4" F NPT	10	150	0.20
16093	1" C x 1" F NPT	10	100	0.30
23358	1-1/4" C x 1-1/4" F NPT	1	50	0.45
23363	1-1/2" C x 1-1/2" F NPT	1	35	0.65
23368	2" C x 2" F NPT	1	25	1.00



## BRONZE ADAPTER FTG x F NPT

Use FTG adapters to transition between copper and male NPT connections.

Stock Code	Part Description	Bag Quantity	Box Quantity	Approx. wt./lb. Each
23238	1/2" FTG x 1/2" F NPT	5	200	0.12
23243	3/4" FTG x 3/4" F NPT	5	150	0.10
23248	3/4" FTG x 1/2" F NPT	5	200	0.15
23258	1-1/4" FTG x 1-1/4" F NPT	1	50	0.47
23263	1-1/2" FTG x 1-1/2" F NPT	1	40	0.61
23268	2" FTG x 2" F NPT	1	20	1.10