

# PROPRESSG



## COPPER ELBOW 90° C x C

Use 90 degree elbows for directional transitions. All fittings come with the Smart Connect Feature.


Stock Code	Part Description	Bag Quantity	Box Quantity	Approx. wt./lb. Each
16128	1/2"	10	100	0.10
16133	3/4"	10	100	0.20
16138	1"	10	100	0.30
16143	1-1/4"	10	50	0.45
16148	1-1/2"	1	25	0.80
16153	2"	1	15	1.15



## COPPER ELBOW 90° FTG x C

Use FTG x C 90 degree elbows for 90 degree directional transitions between ProPress connections. These fittings come with a ProPress connection on one end and a FTG connection on the other. All fittings come with the Smart Connect Feature.

Stock Code	Part Description	Bag Quantity	Box Quantity	Approx. wt./lb. Each
16158	1/2"	10	100	0.10
16163	3/4"	10	100	0.20
16168	1"	10	50	0.25
16173	1-1/4"	1	50	0.40
16178	1-1/2"	1	25	0.80
16183	2"	1	15	1.10



## COPPER ELBOW 45° C x C

Use 45 degree elbows for directional transitions. All fittings come with the Smart Connect Feature.

Stock Code	Part Description	Bag Quantity	Box Quantity	Approx. wt./lb. Each
16188	1/2"	10	100	0.10
16193	3/4"	10	100	0.15
16198	1"	5	50	0.20
16203	1-1/4"	1	50	0.35
16208	1-1/2"	1	40	0.65
16213	2"	1	20	0.85